Cofca

00169.002065. Anna TRACE

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
GRAHAM STONEY	: Examiner:	
Appl. No.: 09/863,434	Group Art Unit: Certificate	
Filed: May 24, 2001	;)	MAR 2 3 2006
For: HIGHLY PIPELINED PRINTING SYSTEM ARCHITECTURE)	of Correction
U.S. Patent No.: 6,954,803 B2	;	
Issued: October 11, 2005) : March 17, 2006	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

03/22/2006 MBEYEHE1 00000019 6954893 01 FC:1811 100.00 OP Patentee's undersigned attorney may be reached in our Costa Mesa, CA office at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank L. Cire
Attorney for Patentee
Registration No. 42,419

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA_MAIN 108709v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,954,803 B2

DATED

October 11, 2005

INVENTOR(S) :

Stoney

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 6, "of;" should read -- of: --; and Line 41, "date" should read -- data --.

COLUMN 6:

Line 30, "the" (first occurrence) should be deleted.

COLUMN 7:

Line 20, "convention" should read -- conventional --; Lines 66 and 67, "Sun Spar-estations" should read -- Sun Sparc-stations --.

COLUMN 8:

Line 49, "directed" should read -- directed in --.

COLUMN 9:

Line 1, "(ie," should read -- (i.e., --;

Line 22, "however" should read -- however, it --;

Line 30, "(ie" should read -- (i.e., --;

Line 43, "(ie." should read -- (i.e., --; and

Line 44, "(eg" should read -- (e.g., --.

CA_MAIN 108705v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. <u>6,954,803 B2</u>

No. of add'l. copies @ 30¢ per page

⇒ _

MAR 24 2006

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,954,803 B2

DATED

October 11, 2005

INVENTOR(S) :

Stoney

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3:

Line 6, "of;" should read -- of: --; and Line 41, "date" should read -- data --.

COLUMN 6:

Line 30, "the" (first occurrence) should be deleted.

COLUMN 7:

Line 20, "convention" should read -- conventional --; Lines 66 and 67, "Sun Spar-estations" should read -- Sun Sparc-stations --.

COLUMN 8:

Line 49, "directed" should read -- directed in --.

COLUMN 9:

Line 1, "(ie," should read -- (i.e., --;

Line 22, "however" should read -- however, it --;

Line 30, "(ie" should read -- (i.e., --;

Line 43, "(ie." should read -- (i.e., --; and

Line 44, "(eg" should read -- (e.g., --.

CA MAIN 108705v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

Form PTO 1050 (Rev. 3-82) (Form#30)

(212) 218-2200 - Facsimile

PATENT NO. 6,954,803 B2

No. of add'l. copies @ 30¢ per page

MAR 24 2006